




Tips for Defect-Free Injection Molding of TPU



Covestro Deutschland AG
CHEMPARK Dormagen
Alte Heerstraße
Building F29
41538 Dormagen
e-mail: info@covestro.com

desmopan.com

This information and our technical advice – whether verbal, in writing or by ways of trial – are given in good faith but without warranty, and this also applies where proprietary rights of third parties are involved. The information is provided by Covestro without assumption of any liability. If any of the above mentioned regulations change after the date of declaration, this declaration is no longer valid. Covestro will strive to keep this information up-to-date. Our advice does not release you from the obligation to verify the information provided – especially that contained in our safety data and technical information sheets –, to check for updates of any information provided by us and to test our products as to their suitability for the intended processes and uses. The application, use and processing of our products and the products manufactured by you on the basis of our technical advice are beyond our control and, therefore, entirely your own responsibility. Our products are sold in accordance with the current version of our General Conditions of Sale and Delivery.

Edition: 2016 · Order-No.: COV00080632 · Printed in Germany

1. Tips for defect-free injection molding of TPU

| | |
|--|----|
| 1.1 Defects in dimensions | 4 |
| 1.2 Demolding defects | 9 |
| 1.3 Color defects | 16 |
| 1.4 Defects in the form of specks and dots | 24 |
| 1.5 Unevenness defects | 25 |
| 1.6 Processing defects | 31 |
| 1.7 Warpage defects | 34 |
| 1.8 Gloss defects | 35 |
| 1.9 Defects in mechanical properties | 44 |
| 1.10 Surface defects | 47 |

Various problems can arise when injection molding thermoplastics – and that goes for TPU, too. We have compiled an extensive list of possible defects, explained their causes and described preventive measures. To help you find them more easily, we have divided the defects into groups, such as “Defects caused by warpage” and “Defects caused by specks and dots”. Please do not hesitate to contact us if this list does not help you solve your problem.

We would be grateful for any hints, suggestions and illustrations you could submit to make this catalogue of defects more complete.




Desmopan®



Texin®



Utechlan®



1.1 Defects in dimensions

Short molding



Description: Molding not completely filled, mostly at end of flow path or thin-walled locations

Causes:

Unsuitable processing parameters

Pressure losses too high in gating system, including hot runner. Sprue, gate and runner cross-sections too small. Pressure loss in hot runner too high. Pressure loss in shut-off nozzle system too high

Wall thickness inadequate


Remedies:

Optimize processing parameters. Increase melt and mold temperatures. Increase injection speed. Switch to holding pressure at a later point in time

Reduce pressure losses in gating system. Increase sprue, gate and runner cross-sections. Check hot runner cross-sections, optimize nozzle point to point. Work with machine nozzle open

Increase wall thickness

4



Flash



Description: Mold gap results in polymer melt penetration on molding

Causes:

Permitted gap width exceeded. Locking force inadequate. Mold rigidity inadequate. Wear of sealing faces

Processing parameters not optimized

Remedies:

Check gap widths. Increase locking force. Increase mold rigidity. Rework sealing faces

Optimize processing parameters. Reduce injection speed or melt temperature. Switch to holding pressure earlier or reduce holding pressure


5

Weight variation

Description: Significant fluctuations in molded part weight and mass


| Causes: | Remedies: |
|--|--|
| Wear in plasticating unit | Check plasticating unit – in particular non-return valve – for wear |
| Mold and melt temperature fluctuations | Check plasticating unit's temperature control units and heating circuits |
| Drying inadequate | Check drying process |
| Metering stroke or melt cushion fluctuates | Check injection molding machine's injection and metering stroke |
| Locking force inadequate | Increase set locking force or select machine with higher locking force |

6



Variations in size

Description: Required dimensions of part not achieved



| Causes: | Remedies: |
|---|--|
| Material too moist | Check material's dryness |
| Predicted shrinkage incorrect | Check shrinkage calculation using details from raw material manufacturer or comparable molds |
| Warpage due to unsuitable design of part or gate position | Check molding for warpage and switch to low-warpage design. Change gate position to obtain uniform orientation |
| Machine and mold not in thermal equilibrium | Check temperature profile of machine and mold for thermal fluctuations |

7

Variations in wall thickness (deviation between nominal and actual values)



Description: Thickness of molded part does not correspond to nominal value or varies greatly and is not within tolerance range

Causes:

Remedies:

Mold rigidity inadequate

Check mold rigidity and reinforce mold if necessary

Shrinkage allowance inaccurate, mold dimensions incorrect

Check mold dimensions, compare with raw material manufacturer's shrinkage data


Cavity pressure too high or locking force too low

Reduce cavity pressure by switching to holding pressure earlier or using a lower holding pressure and increase locking force

Mold centering device defective or worn

Check mold centering device and replace if necessary

8



1.2 Demolding defects

Sprue remains attached



Description: Sprue contracts and / or remains attached to sprue bush or cold runner

Causes:

Remedies:

Unsuitable processing parameters (point at which switch is made from injection to holding pressure, level of holding pressure)

Optimize processing parameters. Reduce cavity pressure by switching to holding pressure earlier and using a lower holding pressure. Check cooling time and increase if necessary

Nozzle radius or aperture too large

Reduce nozzle radius or aperture

Drafts and polishing inadequate

Check components such as machine nozzle, cold runner and gate for undercuts and polishing and rework in the direction of removal (demolding) if necessary. Optimize drafts and polish if necessary

9


Ejector marks

Description: Distinct ejector marks on molding



| Causes: | Remedies: |
|---|---|
| Cavity pressure too high | Optimize injection speed. Reduce holding pressure. Switch to holding pressure earlier |
| Mold rigidity inadequate | Improve mold rigidity |
| Inadequate cooling time or mold temperature locally too high | Optimize cooling / mold temperature control |
| Unsuitable mold design. Excessive undercuts, inadequate draft | Optimize mold design. Reduce undercuts, optimize drafts |
| Inadequate mold (cavity) polishing. Ejector position unsuitable or ejector area too small | Improve mold (cavity) polishing. Optimize ejector position or enlarge ejector area |

10



Noises as mold opens

Description: Opening the mold generates a considerable amount of noise

| Causes: | Remedies: |
|--|--|
| Drafts inadequate | Check mold polishing and drafts, rework if necessary. Use an appropriate mold release agent |
| Mold centering device unsuitable or worn | Improve mold centering |
| Cavity pressure too high | Reduce cavity pressure. Switch from injection to holding pressure earlier. Reduce holding pressure |
| Mold rigidity inadequate | Increase mold rigidity |
| Insufficient release agent | Use release agent batch |

11


Part fractures during removal

Description: Part damaged during removal



| Causes: | Remedies: |
|---|---|
| Cavity pressure too high | Optimize injection speed. Reduce holding pressure. Switch to holding pressure earlier |
| Mold rigidity inadequate | Improve mold rigidity |
| Inadequate cooling time or mold temperature locally too high | Optimize cooling / mold temperature control |
| Unsuitable mold design. Excessive undercuts, inadequate draft | Optimize mold design. Reduce undercuts, optimize drafts |
| Inadequate mold (cavity) polishing. Ejector position unsuitable or ejector area too small | Polish mold surface in direction of removal (demolding), select appropriate coating or roughness height. Improve position and size of ejectors (in particular, locate near corners or under ribs / domes) |
| Inadequate material drying, residence time too long | Check material drying, residence time and melt temperature |

12



Mold fails to open

Description: Even when applying maximum permitted opening force, injection molding machine fails to pull two halves of mold apart

| Causes: | Remedies: |
|-----------------------------|---|
| Cavity pressure too high | Reduce cavity pressure. Switch from injection to holding pressure earlier. Reduce holding pressure. Increase melt temperature within permitted limits |
| Mold rigidity inadequate | Increase mold rigidity |
| Slide valve control failure | Check slide valve is in correct position Tips for opening mold: Use cold water to reduce temperature of mold to room temperature, fit additional hydraulic rams between machine platens to help open mold. If necessary, raise mold temperature above glass transition temperature, pull mold apart |

13


Molded part remains in cavity

Description: Molded part jams, cores / ejectors deform or penetrate part



| Causes: | Remedies: |
|--|--|
| Mold overloaded | Reduce injection speed and holding pressure and switch to holding pressure earlier |
| Excessive undercuts, inadequate drafts | Reduce undercuts, improve drafts |
| Inadequate mold polishing on flanges, ribs or studs | Polish mold surface in direction of removal (demolding) |
| Vacuum between mold surface and molding | Optimize mold venting |
| Premature ejection, molded part sticks or still too soft | Increase cooling time, reduce mold temperature |
| Ejector pins too few in number or poorly positioned | Increase number of ejector pins or optimize their position |

14



Part deformed during removal

Description: Part deformed during removal




| Causes: | Remedies: |
|---|---|
| Cavity pressure too high | Optimize injection speed. Reduce holding pressure. Switch to holding pressure earlier |
| Mold rigidity inadequate | Improve mold rigidity |
| Inadequate cooling time or mold temperature too high locally | Optimize cooling / mold temperature control |
| Unsuitable mold design. Excessive undercuts, inadequate draft | Optimize mold design. Reduce undercuts, optimize drafts |
| Inadequate mold (cavity) polishing. Ejector position unsuitable or ejector area too small | Polish mold surface in direction of removal (demolding), select appropriate coating or roughness height. Improve position and size of ejectors (in particular, locate near corners or under ribs / domes) |

15


1.3 Color defects

Darker color at weld lines

Description: Colored stripe. Darker color occurs at weld lines or near leading / lagging flow fronts fed from neighboring melt streams




| | |
|--|---|
| Causes: | Remedies: |
| Pigment separation or refractive effect due to unsuitable flow at weld lines | Vary flow front speed |
| Overheating of melt, resulting in color changes at weld lines | Reduce thermal melt load |
| Oxidation due to inadequate venting | Improve venting, if necessary by relocating weld line N.B.: Fault tends to occur on light, bright colors such as white, blue, green and orange. |



Homogeneous discoloration

Description: Uniform deviation from basic color, especially with light colors



| | |
|---|--|
| Causes: | Remedies: |
| Melt temperature too high | Check melt temperature and reduce if necessary |
| Inadequate utilization of plasticating unit capacity, resulting in excessive residence time | Use smaller plasticating unit |
| Master batch unsuitable | Use suitable master batch |
| Production stoppage without reduction in temperature | Comply with instructions for production stoppage |

Partial color change

Description: Partial change in color

Causes:

Material not adequately homogenized

Injection and screw speeds too high

Gate too narrow

Residence time too long

Remedies:

Increase back pressure, reduce screw speed


Reduce injection and screw speeds

Widen gate

Shorten residence time by selecting smaller plasticating unit



18



Rings

Description: Rings, bloom effect, matte rings running concentrically to gate

Causes:

Melt flow stagnates in mold, melt temperature too low

Mold temperature too low

Inadequate injection speed

Remedies:

Try to achieve even melt flow, increase melt temperature

Increase mold temperature

Increase injection speed



19

Black (overheating) marks

Description: Streaks and stains from burning, periodic discoloration, dark spots. Brown to black discoloration of molding, at different locations and irregular distances

Causes:


Entrapped, compressed air in injection mold, resulting in burns

Remedies:

Optimize mold venting, in particular near flow lines and at end of flow path. Correct flow front (wall thickness, gate position or flow promoters). Check venting channels. Reduce clamping force. Evacuate mold



20



Black discoloration

Description: Diesel effect. Concentrated black coloring at points where flows merge, e.g. on flanges or studs or in corners at end of flow paths

Causes:

Unfavorable cross-section changes / bends or defective sealing faces, resulting in dead spots where material burns. Dead spots at sealing faces, cross-section changes or bends in hot runne

Remedies:

Check / rework parts and sealing faces affected. Eliminate dead spots. Check weep holes for needle valve system. Check sealing faces. Check direction changes and transition cone

Screw, non-return valve or cylinder wear

Check screw, non-return valve and cylinder for wear

N.B.:

In addition to optical degradation of the molded part, this fault can also damage the mold through corrosion.



21

Stress-whitening

Description: Lighter color in places, with velvety molding surface

Causes:

Overstretching of polymer matrix. Demolding causes excessive mechanical stress. Ejector pins poorly positioned and drafts inadequate

Excessive service load

Cavity pressure too high. Mold rigidity inadequate

Remedies:

Reduce mechanical stress during demolding. Position ejector pins near corners, domes and ribs (in general at stress-whitened lines)

Adapt service loads to material values

Reduce cavity pressure. Increase mold rigidity

N.B.: Fault mostly occurs with thermoplastics containing rubber.

Cloudy appearance

Description: Gray streaks. Molding surface has dark, cloudy appearance

Causes:


Plasticating unit dirty

Wear effects on plasticating unit

Remedies:

Clean plasticating unit.
Reduce screw speed

Replace entire unit or individual (worn) components. Use a plasticating unit with an abrasion- and corrosion-resistant coating



1.4 Defects in the form of specks and dots

Black or brown dots

Description: Specks, either spherical with irregular contours or flaky with sharp, linear contours, occurring sporadically

Causes:

Boundary layers that have formed on screw / cylinder surface damaged / flaking off

Soiling of granules or regranulated scrap


Remedies:

Clean plasticating unit mechanically. Comply with procedures for production stoppages. Check plasticating unit for wear

Check cleanliness of granules. Store granules in a dust-free location. Clean soiled moldings prior to regranulation. Do not regranulate moist or thermally damaged moldings. Check drying and conveyor system for soiling



24



1.5 Unevenness defects

Pockets

Description: Highly localized round or elongated solid swellings – horizontal or vertical – on molded part, not necessarily discernible on both sides

Causes:

Unmelted material or air intake during metering, screw cut too deeply

Unmelted material or air intake during metering, metering stroke greater than 3D (D = diameter)

Unmelted material or air intake during metering, back pressure inadequate

Unmelted material or air intake during metering, melt temperature too low

Unmelted material or air intake during metering, screw speed too high

Remedies:

Use appropriate screw

Select metering stroke between 1 and 3 D

Increase back pressure

Increase melt temperature

Reduce screw speed

25

Delamination

Description: Delamination. Surface layer detaches or flakes off. Can occur over extensive areas of molding or just near sprues

Causes:

Excessive shear stress. Gate too narrow. Injection speed too high

Contamination by incompatible resins

Color batch unsuitable

Remedies:


Reduce shear stress. Widen gates. Reduce injection speed

Clean plasticating unit. Check material in hopper and material supply system for contamination by other materials

Use appropriate color batch



26



Sink marks, localized

Description: Localized, pronounced depression in surface, mostly opposite ribs, at thick-walled locations, cores, weld lines, throats, hot runner nozzles or end of flow paths

Causes:

No compensation for volume contraction during cooling phase

Remedies:

Compensate for volume contraction by adapting wall thickness-rib ratio to material, increasing holding pressure and holding pressure time, and making nozzle aperture and sprue cross-section larger. Reduce melt and mold temperatures (may result in formation of voids). Check melt cushion. If necessary, laminate sink marks



27

Dog's bone effect, extensive sink marks

Description: Extensive contraction of molding away from mold surface except at edges

Causes:


Glass fibers standing up at end of flow path or at weld lines

Holding pressure not sufficiently effective


Remedies:

Change flow front or move weld line to non-critical area

Switch from injection to holding pressure later and increase both holding pressure and holding pressure time



28



Notches along weld line

Description: Pronounced weld line, notch along weld line which can be seen or felt

Causes:

Inadequate mold venting

Inadequate plastic flow properties. Insufficient injection speed. Wall thickness inadequate / flow paths too long

Remedies:

Improve mold venting, especially at end of flow path

Improve flow properties by increasing melt and mold temperatures. Increase injection speed. Increase wall thickness or, if necessary, move gates to shorten flow paths

N.B.:

Fault mostly occurs with high-viscosity or quick-setting thermoplastics. For thermoplastics with a low processing temperature (e. g. PS), weld line can be laminated using the Promold® process.




29

Grooves

Description: Record grooves, stick-slip effect.
In sprue area: Fine, concentric grooves around gate.
In thin-walled areas: Grooves parallel to flow front

| Causes: | Remedies: |
|--|--|
| Melt flow in mold pulsates due to excessive cooling of melt front. | Try to obtain quick, uniform melt flow |
| Injection speed too low | Increase injection speed |
| Melt temperature too low | Increase melt temperature |
| Mold temperature too low | Increase mold temperature |
| Wall thickness too low | Increase wall thickness |

30



1.6 Processing defects

Unusual odor


Description: Pronounced odors, either typical or atypical of material

| Causes: | Remedies: |
|---|--|
| Thermal damage to material. Excessive residence time in cylinder or hot runner. Melt temperature too high | Reduce melt's exposure to heat. Reduce residence time in cylinder or hot runner. Lower melt temperature |

31

Melt cushion fluctuates

Description: Melt cushion varies greatly, sometimes approaching zero



Causes:

Remedies:

Non-return valve defective or worn

Check non-return valve and replace with a new one if necessary


Hydraulics faulty

Check hydraulics are working properly

Uneven metering

Check cylinder barrel for wear and if necessary fit bush or use new plasticating unit

32



Cycle too long

Description: Actual cycle time exceeds scheduled cycle time

Causes:

Remedies:

Metering time too long

Cut metering time. Increase screw speed to maximum peripheral velocity of 0.25 m / s. Use larger plasticating unit. Check plasticating unit for wear. Use more efficient screw

Cooling time too long

Cut cooling time. Reduce mold temperature within permitted limits. Improve cooling, targeting critical areas

Handling time too long

Improve handling system

33

1.7 Warpage defects

Warpage, general

Description: Moldings not as shown in drawing, distorted or do not fit together accurately

Causes:

Unsuitable design of part. Unsuitable glass fiber orientation. Unsuitable wall thickness distribution

Holding pressure not sufficiently effective.
Non-return valve worn

Remedies:


Optimize design of molding. Improve glass fiber orientation by optimizing gate. Optimize wall thickness distribution

Switch from injection pressure to holding pressure later and increase holding pressure. Check non-return valve and replace if necessary

N.B.: Possible causes of defect, associated remedies and their interdependencies are too complex to go into here.



34



1.8 Gloss defects

Frosting

Description: Rough, matt part surface

Causes:

Injection speed inadequate


Mold temperature too low

Remedies:

Increase injection speed

Increase mold temperature. Equip mold with thermal insulation. Use more efficient temperature-control unit

N.B.: Only affects glass-fiber-reinforced thermoplastics. Very evident on amorphous thermoplastics, less so on semi-crystalline thermoplastics




35

Gloss level not achieved on polished surface

Description: Molding fails to achieve required gloss level either over entire surface or in a specific area

| Causes: | Remedies: |
|--|--|
| Mold polishing inadequate or worn | Improve mold polishing |
| Inadequate injection speed, possibly due to poor venting | Increase injection speed, if necessary by improving venting |
| Fluctuating mold temperature due to insufficient cooling | Check mold for uniform temperature |
| Inadequate material drying | Check drying process |
| Holding pressure not sufficiently effective | Increase holding pressure and holding pressure time. If necessary, widen gates |

36



Gloss differential on molded part surface

Description: Different gloss levels, either over entire molded part or at various locations

| Causes: | Remedies: |
|---|--|
| Inadequate injection speed | Increase injection speed |
| Mold surface worn or corroded | Rework mold surface |
| Fluctuating mold temperatures. Fault in heating / cooling circuit, e.g. leak, heating / cooling channel blocked, temperature control unit not working | Service temperature control system and repair leak if necessary. Improve temperature control with additional heating / cooling channels, by increasing heating / cooling medium throughput or by changing this medium (water instead of oil) |



37

Localized, shiny, finger-like hollows

Description: Shiny hollows, often near sprues, at cores or close to hot runner elements, often assumed to be bonding spots

Causes:

Premature ejection

Inadequate holding pressure and holding pressure time

Premature switch to holding pressure

Localized excessive mold temperature

Remedies:


Extend cycle time

Increase holding pressure, extend holding pressure time, check melt cushion. Check nozzle aperture, sprue cross-section and gate cross-section and widen if necessary


Switch to holding pressure later

Lower mold temperature on a localized basis using additional cooling channels or separate temperature control

N.B.:
See also "Matt surface defects"



38



Dull spots

Description: Matt halo, dull spot. Uniform, well-defined velvety area

Causes:

Speed differences between flow fronts (if several injection points)

Tearing of already solidified outer skin at sharp bends or sudden changes in wall thickness

Remedies:

Even out speed differences by balancing gating system (if several injection points)

Round off or polish changes in wall thickness and transitions in gate / mold or adjust flow front speed

N.B.:
See also "Flaking"



39

Matt surface defects at hot runner elements

Description: Rough, cracked surface, creating a matt effect close to hot runner elements or at hot cores

Causes:

Premature ejection

Mold temperature too high at hot runner

Core temperature too high

Remedies:

Extend cooling time

Improve thermal separation of hot runner, reduce mold temperature

Ensure adequate cooling of core



40

Matt appearance not achieved on textured surface

Description: Required matt appearance not achieved on surface of molding

Causes:

Injection speed and mold temperature too low

Holding pressure not sufficiently effective

Surface texture inadequate or worn

Remedies:

Increase injection speed and mold temperature

Switch to holding pressure later and increase holding pressure

Rework mold surface



41

Damage to grain on molded part

Description: Cracked, rough surface with scoring in direction of removal (demolding), mostly at same location

Causes:

Inadequate drafts

Mold surface damaged


Cavity pressure too high

Reduce cavity pressure. Switch from injection to holding pressure earlier. Reduce holding pressure. Optimize injection speed. Increase melt temperature within permitted limits

Inadequate mold rigidity

Increase mold rigidity

N.B.:
Scoring can often only be identified using optical aids.



42

White patches

Description: Whitish, rough, flaky patches or whitish round or oval patches resembling mildew

Causes:

Material too moist

Melt temperature too high, residence time in cylinder and hot runner too long

Remedies:

Check dryer / drying process

Check melt temperature, melt residence time and screw speed and reduce if necessary



43

1.9 Defects in mechanical properties

Weld line strength insufficient

Description: Part failure near weld line

Causes:


Insufficient mold venting

Inadequate plastic flow properties. Injection speed too low. Wall thickness inadequate / flow paths too long


Remedies:

Improve mold venting

Improve flow properties. Increase injection speed. Increase melt and mold temperatures. Increase wall thickness or relocate gates if necessary to shorten flow paths



44



Defective integral hinges

Description: Integral hinges tear or break under stress

Causes:

Incorrect material selection, e.g. amorphous thermoplastics

Weld line in unsuitable position in integral hinge

Remedies:

Use a suitable semi-crystalline thermoplastic

Change weld line and comply with design guidelines for integral hinges



45

Mechanical problems with part



Description: Molding not up to mechanical requirements

Causes:

Remedies:

Excessive mechanical stress

Check dimensioning meets mechanical requirements. Check molded parts' internal stress levels (if necessary, increase mold and melt temperatures, reduce cavity pressure). Check plastics' resistance to media

Material degradation due to incorrect drying or overexposure to heat

Check melt temperature, residence time and drying process


Weld line in unsuitable position

Locate weld line outside area where main stress occurs

Poor demolding behavior at domes and screw connections


Avoid damaging part during removal (demolding), improve removal behavior by polishing mold

46



1.10 Surface defects

Flaking



Description: Cold displacement. Surface looks flaky with alternating shiny and matt areas, mostly near sprues

Causes:

Remedies:

Displacement of already cooled material

Inject in stages – slow to fast. Reduce mold temperature. Provide gates with radii and polish

47

Jetting

Description: Jetting. Melt which has entered cavity first is visible on part surface (mostly S-shaped). Fault occurs near sprues or at throats

Causes:

Unsuitable gate or throat with result that no frontal flow is produced. Gate position has no deflector surface.
Gate cross-section or throat too small

Injection speed too high


Remedies:

Change gate. Select gate position with deflector surfaces. Make gate cross-section larger.
Improve design of changes in diameter

Give preference to injection in stages – slow to fast.



48



Extensive silver streaks

Description: Extensive elongated penicillate streaks

Causes:

Plasticating unit's metering stroke too high

Remedies:

Use larger plasticating unit to reduce metering stroke (>3D). If plasticating unit cannot be changed, increase feed section temperature, reduce screw speed, increase cycle time and if necessary increase size of melt cushion, if possible by 1-2 D, as an additional remedial measure

Optimize plasticating conditions. Increase back pressure within permitted limits. Shorten screw retraction. Let machine nozzle contact hot runner mold

Air intake during metering

N.B.:

Fault sometimes occurs in association with blistering.



49

Buckling line

Description: Depending on angle of light, clearly discernible line or shimmering area on part, often at weld lines, ribs, sudden changes in wall thickness or slide valves

Causes:

Spring-loaded gate valves

Glass fibers standing up at weld lines

Sudden changes in rigidity at ribs or sudden changes in wall thickness

Remedies:


Improve gate valve support / mold rigidity

Change position of weld line, if necessary also using sprue position and number of gates

Avoid sudden changes in wall thickness and provide gradual transitions



50



Large bubbles

Description: Hollow bubbles filled with air in wall



Causes:

Air intake during metering

Capacity utilization of plasticating unit too high

Remedies:

Check granule conveying system for air intake. Increase back pressure within permitted limits. Shorten screw retraction

If screw stroke exceeds 3D, use plasticating unit one size larger

51

Linear surface damage

Description: Scoring, scratches. Scoring or scratches on part surface running in direction of removal (demolding), also visible as matt stripes on high-gloss surface

Causes:

Mold's surface texture damaged

Spring-loaded gate valves

Excessive cavity pressure

Inadequate mold rigidity

Remedies:

Check mold's surface texture and rework if necessary, polish in direction of removal

Optimize slide valves


Reduce cavity pressure. Switch from injection to holding pressure earlier. Reduce holding pressure. Optimize injection speed. Increase melt temperature within permitted limits

Reinforce mold

N.B.:
See also "Noises as mold opens"



52



Streaks open towards flow direction

Description: Moisture streaks. U-shaped, elongated, tufted streaks, open towards flow direction; in a less pronounced version in the form of small lines

Causes:

Residual moisture content of pellets too high

Remedies:

Check drying process (drying temperature and time and hourly throughput). Check dryer for soiled filters. Check drive motor's direction of rotation



53

Streaks due to overheating, needle-like streaks

Description: Silver streaks. Elongated silvery streaks



Causes:

Overheating of melt, melt temperature too high

Overheating of melt, melt residence time too long

Overheating of melt, screw speed too high

Overheating of melt, nozzle and runners too narrow

Overheating of melt, production stoppage without reduction in temperature

Remedies:

Reduce thermal stress on melt, lower melt temperature

Reduce thermal stress on melt, select smaller screw diameter


Reduce thermal stress on melt, lower screw speed

Reduce thermal stress on melt, widen nozzle and runners

Reduce thermal stress on melt, comply with instructions for production stoppage

N.B.:
Fault often similar to moisture streaks.

54



Tear drops

Description: Air-filled hook. Lines in shape of hook / tear drop caused by trapped air



Causes:

Air rolled over and trapped in injection mold, e.g. from engravings, grooves or depressions

Remedies:

Reduce injection speed in critical area. Improve mold venting close to flow lines and near depressions, flanges or engravings. Evacuate mold

55


Cold slug

Description: Cold-flow mark. Well-defined, irregular matte area. Cold melt particles entrapped in surface of molding



| Causes: | Remedies: |
|--|--|
| Ejector claw on cold runner rod missing or too small to absorb cold slug | Provide or optimize ejector claw so that cold slug is absorbed |
| Melt leaking from machine nozzle or hot runner | Increase screw retraction, optimize thermal separation in hot runner |
| Nozzle aperture and heating inadequate | Make nozzle aperture larger, install band heater with higher capacity, check thermocouple and controller |

56



Small bubbles

Description: Entrapped air similar to voids but greater in number and with much smaller diameters



| Causes: | Remedies: |
|-------------------------|---|
| Material too moist | Check drying process |
| Unsuitable vented screw | Select appropriate vented screw or replace vented screw with normal one and pre-dry material N.B.: Fault often coincides with silver streaks. |

57

Craters

Description: Pinholes, pimples. Depressions the size of pinpricks



Causes:

Remedies:

Material degradation

Reduce melt temperature and residence time


Pigment has detrimental effect (use of incompatible pigments for in-plant coloring, often wrong type of carbon black)

Use compatible pigments or different type of carbon black

Proportion of carbon black too high

Reduce proportion of carbon black

58



Gray dots

Description: Metal specks. Gray foreign particles which may appear shiny, depending on angle of light



Causes:

Remedies:

Plasticating unit worn

Check plasticating unit for screw, cylinder or non-return valve wear

Foreign bodies due to feed pipe, container and feed hopper abrasion

Check pipes, containers and feed hoppers for abrasion. Make such pipes, containers and hoppers from stainless steel – aluminum and tinplate are unsuitable. Avoid bends as far as possible, otherwise design with large radii

Granulator for producing reclaim worn

Check granulators regularly for abrasion / damage and repair when necessary

59

Microscopic cracks

Description: Fine, microscopic cracks in molded part, often just on surface of outer fibers under tensile stress

Causes:

Stress levels too high in molded part


Contact with inappropriate media

Remedies:

Optimize processing parameters with regard to stress levels. Increase mold and melt temperatures. Design molding to reduce long-term outer fiber strain

Check media compatibility. Check release and anti-corrosion agents to see if they cause stress cracking. Check molded parts for chemical resistance to cleaning / degreasing agents. Check resistance to media used and reduce load if necessary

60



Voids

Description: Vacuole, bubble. Round or elongated bubbles (hollow vacuums), generally only discernible on transparent or translucent parts

Causes:

No compensation for volume contraction during cooling phase. Holding pressure not sufficiently effective

No compensation for volume contraction during cooling phase. Unsuitable injection position or part design

Remedies:

Increase holding pressure, extend holding pressure time, check melt cushion. Check nozzle aperture, sprue cross-section and gate cross-section and make larger if necessary

Inject in thick-walled area. Revise wall thicknesses to avoid excessive changes in thickness

N.B.:

Comply with design guidelines for injection molded parts




61

Notes

12 horizontal dotted lines for writing notes.

62




12 horizontal dotted lines for writing notes.

63

Notes

Handwriting practice area for page 64, consisting of 12 horizontal dotted lines.

64



Handwriting practice area for page 65, consisting of 12 horizontal dotted lines.

65